




$n_d - \nu_d$  Diagram **GMO**



$H_k - FA$  (Knoop Hardness-Abrasion Factor) Diagram



$n_e - \nu_e$  Diagram



$P_{g,F} / \nu_d$  Diagram

